



# ASNU TIPS

65 – 67 Glencoe Road, Bushey, Herts, WD23 3DP UK

Tel: (44) 208 420 4494

E-Mail: [enquiries@asnu.com](mailto:enquiries@asnu.com) Web: [www.asnu.com](http://www.asnu.com)

(06/2019)

## Sagem "Mini" Injector

These injectors can suffer with water damage to the internal disc controlling the flow of the injector. This can even be caused by condensation in the fuel tank. Unfortunately, cleaning will not resolve these problems and in some cases it can make the problem worse, so if these injectors show any signs of poor performance, they should be replaced. We recommend a Bosch replacement injector as shown below.



← **Sagem**  
(problem injector)



↑  
How the disc  
should look

Damage caused  
by water  
contamination



Recommended Bosch  
replacement injector

